

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ILLINOIS WATERWAY, DRESDEN ISLAND LOCK AND DAM
7521 North Lock Road
Channahon vicinity
Will County
Illinois

HAER IL-I64-F

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Brian Grogan, photographer, October 2007

IL-164-F-1	CONTROL STATION AND LOCK. LOOKING EAST.
IL-164-F-2	CONTROL STATION. DAM AT LEFT REAR. LOOKING NORTH NORTHEAST.
IL-164-F-3	UPSTREAM LOCK GATE INTERIOR. LOOKING NORTH NORTHEAST.
IL-164-F-4	LOCK VIEW. CONTROL STATION AT CENTER REAR. LOOKING EAST.
IL-164-F-5	LOCK VIEW. DAM AT RIGHT REAR. CONTROL STATION AT RIGHT. LOOKING EAST.
IL-164-F-6	EXTERIOR OF DOWNSTREAM LOCK GATES. LOOKING EAST.
IL-164-F-7	DOG HOUSE AND DOWNSTREAM LOCK GATE. LOOKING NORTH NORTHEAST.
IL-164-F-8	BARGES WAITING TO ENTER DOWNSTREAM LOCK GATE. LOOKING WEST.
IL-164-F-9	DOWNSTREAM LOCK GATE IN CLOSED POSITION. LOOKING NORTH.

ILLINOIS WATERWAY, DRESDEN ISLAND LOCK AND DAM
HAER IL-164-F
INDEX TO PHOTOGRAPHS

IL-164-F-10	DOWNSTREAM LOCK GATE IN OPEN POSITION. LOOKING NORTH.
IL-164-F-11	DOWNSTREAM LOCK GATE IN OPEN POSITION WITH BARGES IN TRANSIT. LOOKING NORTH.
IL-164-F-12	DOWNSTREAM LOCK GATE DETAIL VIEW WITH DOG HOUSE. NOTE CONTROL ARM AND GEAR FOR GATE. LOOKING NORTHWEST.
IL-164-F-13	PART ONE OF TWO PART PANORAMA WITH NO. IL-164- F-14. RIVER AND DAM. LOOKING NORTH NORTHEAST.
IL-164-F-14	PART TWO OF TWO PART PANORAMA WITH NO. IL -164-F-13. OUTER LOCK WALL, LOCK, AND TUG BOAT. CONTROL HOUSE AT RIGHT REAR. LOOKING EAST.
IL-164-F-15	VIEW OF DOWNSTREAM SIDE OF DAM. LOOKING NORTH NORTHEAST.
IL-164-F-16	DETAIL VIEW OF DOWNSTREAM SIDE OF DAM. LOOKING NORTH.
IL-164-F-17	DETAIL VIEW OF TAITER GATE. LOOKING WEST.